










Package List Of C9372 Brake Lathe

No	Description	Part No	Qty	Chart
1	Main Machine	C7-02-00	1set	
2	Bench with 10 piece hooks	C7-01-00 C4F-01-12	1 set	
3	Twin Cutter	C7-02-05-00	1 set	
4	Arbor(1"/25.4mm) with nut and combination washer	C4-00-42 C4-00-48A C4-05-00 C4-00-47	1 set	
5	Plastic Safety Shield	C7-02-05-06	1	
6	Open End Wrench 27-30mm		1	
7	Square Wrench		1	
8	Location Cone 25.4X73.5mm	C7-02-09	1	
9	Cutting Bar	C4-10-0C C4-9-9-0C C4-9-10-0C	3	
10	Silencing Belt For rotor and drum	C4F-4-0 C4-12-0	2	
11	Taper Cone (45x70mm)	C4-00-44-03 (For 1"Arbor)	1	

Package List Of C9372 Brake Lathe

No	Description	Part No	Qty	Chart
12	Taper Cone (59x75mm)	C4-00-44-04 (For 1"Arbor)	1	
13	Taper Cone (66x82mm)	C4-00-44-05 (For 1"Arbor)	1	
14	Taper Cone (74x90mm)	C4-00-44-06 (For 1"Arbor)	1	
15	Spacer (25.4、50.8、50.8mm)	C7F-24 C7F-26 (For 1"Arbor)	3	
16	Hub Localize (Arbor 2"/50.8mm)	C8F-01-01	1	
17	Localizer Big Taper Cone (79x108mm)	C8F-01-02 (For 2"Arbor)	1	
18	Localizer Small Taper Cone (54x82.5mm)	C8F-01-03 (For 2"Arbor)	1	
19	Nut	C8F-01-04 (For 2"Arbor)	1	
20	Big Spacer (171.5mm)	C8F-02 (For 2"Arbor)	1	
21	Small Spacer (133mm)	C8F-03 (For 2"Arbor)	1	
22	Big Adapter (171.5mm)	C8F-04-00 (For 2"Arbor)	1	

Package List Of C9372 Brake Lathe

No	Description	Part No	Qty	Chart
23	Small Adapter (133mm)	C8F-05-00 (For 2" Arbor)	1	
24	Step Adapter (25.4x50.8mm)	C8F-06 (For 2" Arbor)	1	
25	Spring	C4-00-45 (For 1" Arbor)	1	
26	Bend Wrench 78-85		1	
27	Clamp (94mm)	C4-00-46-01 (For 1" Arbor)	2	
28	Clamp (116mm)	C4-00-46-02 (For 1" Arbor)	2	
29	Clamp (146mm)	C4-00-46-03 (For 1" Arbor)	2	
30	Chip Bin	C7-03-00	1set	
31	A Lamp with Three Batteries		1	